

BUILDING SAFETY CERTIFICATE

NO. T.S / Building Safty/Multai/2023-24

Dated : 01/02/2024

It is to Certified that the existing building of **R.D. PUBLIC SCHOOL**, at Multai Distt. Betul (M.P.) comprised of School block Ground Floor, First Floor, Second Floor & Third Floor Owned / Occupied by, "**OM SIKHSHAN SAMITI, KAMATH**" Tehsil - Multai Distt. Betul, M.P. have complied with the Building Bye Laws in accordance with the rule of State / UT, and incorporate the Provisions of building safety as specified in National Building code 2005,2016 and as ammended Rules, there after and has been verified by the officers concerned **Er.R.K. Rai, Sub Divisional Officer, P.W.D., Sub Division Multai Distt. Betul** on dated **25/01/2024** in the presence of **Shri Dheerendra Agrawal** Director R.D. Public School Kamath, and that the building/ premises is Safe & fit for running School and occupancy **upto classes XII with effect from 01/02/2024** for a period of **One years (ie.31/03/2025)** in accordance with rule and subject to compliance of the specific conditions as appended.

Remarks :-

- 1 Opening Safe
- 2 Fire extinguisher sufficient
- 3 Both male & Female Toilet present
- 4 Parking Facilities available.

Issued on 01/02/2024 at Multai by

Signature with Seal :

[Handwritten Signature]
 Name: **Er. R.K. Rai** Sub division
 Designation : **Sub Divisional Officer**

Name & Address of Department/Office: **P.W.D. Sub Division Multai.**

(Assistant Engineer & above Officer of concerned Govt. Department only).

*Strike out whichever is not applicable.

[Handwritten Signature]
Executive Engineer
 P.W.D. Betul Division
 Betul (M.P.)

[Handwritten Signature]
PRINCIPAL
 R.D. PUBLIC SCHOOL
 MULTAI, BETUL (M.P.) 460661

[Handwritten Signature]
Manager
 R.D. Public School
 Multai

INSPECTION REPORT OF SUB ENGINEER P.W.D. (B&R) SUB DIVISION MULTAI

OFFICE REF.

NAME OF SCHOOL :- R.D.PUBLIC SCHOOL MULTAI
NAME OF BUILDING :- SCHOOL BLOCK
TUPE OF STRUCTURE :- R.C.C. STRUCTURE


ABOVE MENTION BUILDING IS INSPECTED BY ME ON ABOVE MENTIONED DATE IN PHYSICALI INSPECTION CONDITION OF VARIOUS ROOM ARE MENTIONED BELOW


SCHOOL BLOCK DETAILS


FLOOR	CONDITION OF ROOM	NO. OF ROOM
GROUND FLOOR	GOOD CONDITION	14Nos. With Toilet
FIRST FLOOR	GOOD CONDITION	14Nos. With Toilet
SECOND FLOOR	GOOD CONDITION	14Nos. With Toilet
THIRD FLOOR	GOOD CONDITION	14Nos. With Toilet

HENCE PHYSICAL INSPECTION IT IS FOUND THAT BUILDING STRUCTURE IS SAFE FOR USE IN EVEN CLIMATE CONDITION AND REPORT SUBMITTED TO, SUB DIVISIONAL OFFICER TO FURTHER ACTION.

ENCLOSURE:-


SUB ENGINEER
P.W.D.(B&R) SUB DIVISION
MULTAI


SUB DIVISIONAL OFFICER
P.W.D.(B&R) SUB DIVISION
MULTAI

45

EXECUTIVE ENGINEER
P.W.D. (B&R) DIVISION
Betul (M.P.)
BETUL


PRINCIPAL
R.D. PUBLIC SCHOOL
MULTAI, BETUL (M.P.) 460661


Manager
R.D.Public School
Multai

BUILDING SAFETY CERTIFICATE

NO. T.S / Building Safty/Multai/2023-24

Dated : 01/02/2024

It is to Certified that the existing building of **R.D. PUBLIC SCHOOL**, at Multai Distt. Betul (M.P.) comprised of Admin block Ground Floor, First Floor, Owned / Occupied by, "**OM SIKHSHAN SAMITI, KAMATH**" Tehsil -Multai Distt. Betul, M.P. have complied with the Building Bye Laws in accordance with the rule of State / UT ,and incorporate the Provisions of building safty as specified in National Building code 2005,2016 and as ammended Rules, there after and has been verified by the officers concerned **Er.R.K. Rai, Sub Divisional Officer, P.W.D.,** Sub Division Multai Distt. Betul on dated **25/01/2024** in the presence of **Shri Dheerendra Agrawal** Director R.D. Public School Kamath, and that the building/ premises is Safe & fit for running School and occupancy **upto classes XII with effect from 01/02/2024** for a period of **One years (ie.31/03/2025)** in accordance with rule and subject to compliance of the specific conditions as appended.

Remarks :-

- 1 Opening Safe
- 2 Fire extinguisher sufficient
- 3 Both male & Female Toilet present
- 4 Parking Facilities available.

Issued on 01/02/2024 at Multai by

Signature with Seal :

[Handwritten Signature]
 Sub. Divisional Officer
 P.W.D. (BIR) Sub division
 MULTAI

Name: **Er.R. K. Rai**Designation : **Sub Divisional Officer**Name & Address of Department/Office: **P.W.D. Sub Division Multai.**

(Assistant Engineer & above Officer of concerned Govt. Department only).

*Strike out whichever is not applicable.

[Handwritten Signature]
Executive Engineer
 P.W.D. Betul Division
 Betul (M.P.)

[Handwritten Signature]
PRINCIPAL
 R.D. PUBLIC SCHOOL
 MULTAI, BETUL (M.P.) 460661

[Handwritten Signature]
Manager
 R.D. Public School
 Multai

INSPECTION REPORT OF SUB ENGINEER P.W.D. (B&R) SUB DIVISION MULTAI

OFFICE REF.

NAME OF SCHOOL :- R.D.PUBLIC SCHOOL MULTAI
NAME OF BUILDING :- ADMIN BLOCK
TUPE OF STRUCTURE :- R.C.C. STRUCTURE


ABOVE MENTION BUILDING IS INSPECTED BY ME ON ABOVE MENTIONED DATE IN PHYSICAL INSPECTION CONDITION OF VARIOUS ROOM ARE MENTIONED BELOW


ADMIN BLOCK DETAILS



FLOOR	CONDITION OF ROOM	NO. OF ROOM
GROUND FLOOR	GOOD CONDITION	10Nos. With Toilet
FIRST FLOOR	GOOD CONDITCN	7Nos. With Toilet

HENCE PHYSICAL INSPECTION IT IS FOUND THAT BUILDING STRUCTURE IS SAFE FOR USE IN EVEN CLIMATE CONDITION AND REPORT SUBMITTED TO, SUB DIVISIONAL OFFICER TO FURTHER ACTION.

ENCLOSURE:-


SUB ENGINEER
P.W.D.(B&R) SUB DIVISION
MULTAI


SUB DIVISIONAL OFFICER
Sub Divisional Officer
P.W.D. (B&R) SUB DIVISION
MULTAI



EXECUTIVE ENGINEER
P.W.D. (B&R) DIVISION
Betul (M.P.)
BETUL


PRINCIPAL
R.D. PUBLIC SCHOOL
MULTAI, BETUL (M.P.) 460661


Manager
R.D. Public School
Multai